

Assessment of Dam Safety of Coal Combustion Surface Impoundments

Indianapolis Power & Light Company

Eagle Valley Generating Station

4040 Blue Bluff Road

Martinsville, Indiana

Prepared for:

U. S. Environmental Protection Agency

Washington, D. C.

June 4, 2010

CDM Project No.: 76658.1801.034.SIT.EAGLE

Draft Report

Preface

The assessment of the general condition of the impoundments is based upon available data and visual observations. Detailed investigations and analyses involving topographic mapping, subsurface investigations, testing and detailed computational evaluations are beyond the scope of this report.

In reviewing this report, it should be realized that the reported condition of the impoundments is based on observations of field conditions at the time of assessment, along with data made available to the assessment team. In cases where an impoundment may have been lowered or drained prior to the assessment, such action, while improving the stability and safety of the impoundment, removes the normal load on the structure and may obscure certain conditions, which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is critical to note that the condition of impoundments depends on numerous and constantly changing internal and external conditions and is evolutionary in nature. It would be incorrect to assume that the present condition of the impoundment at the time of the assessment is representative of the condition of the impoundment at some point in the future. Only through continued care and assessment can there be any chance that unsafe conditions will be detected.

Prepared By:

CDM

I certify that the management unit (s) referenced herein have been assessed on April 28 and 29, 2010:



Michael L. Schumaker, P.E.
Senior Geotechnical Engineer
PE10708838



Michael P. Smith, E.I.T.
Geotechnical Engineer

CDM



Contents

Section 1	Introduction and Project Description	
1.1	Introduction.....	1-1
1.2	State Regulation	1-1
1.2.1	Permits	1-1
1.3	Datum.....	1-1
1.4	Site Description and Location.....	1-2
1.4.1	CCW Impoundment Construction and Historical Information.....	1-2
1.4.2	Current CCW Impoundment Configuration.....	1-3
1.4.3	Other Impoundments	1-5
1.5	Previously Identified Safety Issues	1-5
1.5.1	February 14, 2007 Failure.....	1-5
1.5.2	January 30, 2008 Failure.....	1-6
1.6	Site Geology.....	1-6
Section 2	Field Assessment	
2.1	Visual Observations	2-1
2.2	Pond A.....	2-2
2.2.1	Exterior Slope	2-2
2.2.2	Crest.....	2-3
2.2.3	Interior Slope.....	2-3
2.2.4	Outlet Pipes	2-3
2.3	Pond B	2-3
2.3.1	Exterior Slope	2-3
2.3.2	Crest.....	2-4
2.3.3	Interior Slope.....	2-4
2.3.4	Outlet Pipes	2-4
2.4	Pond C.....	2-4
2.4.1	Exterior Slope	2-4
2.4.2	Crest.....	2-4
2.4.3	Interior Slope.....	2-4
2.4.4	Outlet Structure	2-5
2.5	Pond D.....	2-5
2.5.1	Exterior Slope	2-5
2.5.2	Crest.....	2-6
2.5.3	Interior Slope	2-6
2.5.4	Diversion Embankment.....	2-6
2.5.5	Breached Section and Remedial Construction	2-6
2.5.6	Toe Drain	2-7
2.6	Pond E	2-7
2.6.1	Exterior Slope	2-7
2.6.2	Crest.....	2-7

2.6.3 Interior Slope	2-7
2.6.4 Breached Section and Remedial Construction	2-7
2.6.5 Outlet Structure	2-8
Section 3	Data Evaluation
3.1 Design Assumptions	3-1
3.2 Hydrologic and Hydraulic Design.....	3-1
3.3 Structural Adequacy and Stability	3-1
3.3.1 Pond A, Pond B & Pond C.....	3-2
3.3.2 Pond D & Pond E.....	3-2
3.4 Foundation Conditions	3-4
3.5 Operations and Maintenance.....	3-4
Section 4	Conclusions and Recommendations
4.1 Hazard Classification.....	4-1
4.2 Acknowledgement of Impoundment Condition	4-2
4.3 Maintaining and Controlling Vegetation Growth.....	4-2
4.4 Erosion Protection and Repair	4-2
4.5 Impoundment Hydraulic and Stability Analysis.....	4-3
4.6 Remedial Design.....	4-3
4.7 Inspection Recommendations.....	4-3
Section 5	Closing
Section 6	References
Tables	
Table 1	Approximate Precipitation Prior to Site Visit.....2-1
Table 2	Minimum Safety Factors Required
Table 3	FMSM – Pond D & E Soil Parameters.....3-3
Table 4	BT ² – Pond D & E Soil Parameters.....3-3
Table 5	Recommended Impoundment Hazard Classification Ratings
Figures	
Figure 1	Locus Plan
Figure 2	Downstream Area
Figure 3	Typical Cross-sections Ponds A, B & C
Figure 4	Typical Cross-sections Ponds D & E
Figure 5	Aerial Map
Figure 6a	Photograph Location Plan
Figure 6b	Photograph Location Plan

Figures

- Figure 7* Divider Embankment D/E Slope Stability Analyses
 performed by FMSM
- Figure 8* BT² Slope Stability Analyses
- Figure 9* Typical Bi-weekly inspection checklist

Appendices

- Appendix A – USEPA Coal Combustion Dam Inspection Checklist Forms*
- Appendix B – Photographs*
- Appendix C – Photo GPS Locations*

DRAFT

Section 1

Introduction & Project Description

1.1 Introduction

CDM was contracted by the United States Environmental Protection Agency (USEPA) to perform site assessments of selected coal combustion waste (CCW) surface impoundments. As part of this contract, CDM performed a site assessment of five CCW impoundments at the Eagle Valley (EV) Generating Station, owned and operated by Indianapolis Power & Light Company (IPL).

The EV Generating Station is located within the Town of Martinsville, Morgan County, Indiana as shown on [Figure 1](#). The state boundary with Illinois and Kentucky is approximately 60 miles west and 92 miles south of the site, respectively. The Town of Martinsville, Indiana is approximately five miles downstream (southwest) of the site as shown on [Figure 2](#).

CDM made a site visit to the EV Generating Station on April 28 and 29, 2010 to collect relevant information, inventory the impoundments, and perform visual assessments of the impoundments. CDM representatives Michael L. Schumaker, P.E. and Michael P. Smith were accompanied by the following individuals:

<u>Company</u>	<u>Name and Title</u>
IPL	Nysa L. Hogue, Senior Environmental Coordinator
IPL	David B. Abrams, Technical Services Team Leader
IPL	Rick Jacobs, Lead Engineer
IPL	J. Kyle Noah, Environmental Team Leader

1.2 State Regulation

The Indiana Department of Natural Resources (IDNR) Water Division is responsible for the State's dam safety program. It is our understanding that to date IDNR has not been actively involved in the regulation of CCW impoundments. IPL staff stated there are no State inspection reports for the impoundments at EV Generating Station.

1.2.1 Permits

The IPL EV Generating Station was issued a permit under the National Pollutant Discharge Elimination System (NPDES) authorizing discharge to the White River in accordance with effluent limitations, monitoring requirements, and other conditions set forth in the permit. The station's current permit will expire December 31, 2011. The permit number is IN0004693.

1.3 Datum

Elevations are referenced to the National Geodetic Vertical Datum of 1929 (NGVD 29). Directional coordinates are referenced to magnetic north.

1.4 Site Description and Location

1.4.1 CCW Impoundment Construction and Historical Information

The EV Generating Station began operation in February 1949. The CCW is generated by Unit 3 (on line since 1949), Units 4 and 5 (on line since 1953), and Unit 6 (online since 1956). Approximately 2,500 tons of coal is burned daily producing approximately 250 tons of CCW.

The original CCW impoundment was constructed between 1947 and 1949. The impoundment was constructed in the vicinity of the footprint of current Ponds A, B and C to the west of the Pennsylvania Railroad tracks. A typical cross-section of the embankment is presented in [Figure 3](#). The original embankment was constructed with native site soils to approximately 4 to 5 feet above existing grades to a crest elevation of approximately El. 608. The embankment had a 10-foot-wide crest and 1.5 Horizontal:1 Vertical (1.5H:1V) side slopes.

In 1956, a second impoundment was constructed south of the original pond. The footprint of the second impoundment extended to the southern property line and was adjacent to the railroad. The embankment was constructed above existing grade with native soil to a crest elevation of approximately El. 608. The embankment had a 10-foot-wide crest and 1.5H:1V side slopes.

In addition, a third impoundment was constructed east of the railroad in the current footprint of Ponds D and E. The embankment was constructed approximately 1 to 7 feet above existing site grades with native soil to a crest elevation of approximately El. 612. The embankment had a 10-foot-wide crest with 1.5H:1V side slopes. An overflow weir was constructed along the western embankment to allow water to flow into the adjacent western impoundments.

Between 1962 and 1970, the east impoundment embankment was raised multiple times with compacted ash until the crest reached elevation El. 625.

In about 1979, the west impoundments were reconfigured to create the current footprint of Ponds A, B and C. The reconfiguration occurred within the footprint of the existing west impoundments, and the crest was raised to approximately elevation El. 610. In 1980 the crest was raised to elevation El. 619 around the perimeter using compacted ash. The embankment had a 10-foot-wide crest and 2H:1V side slopes on the interior and 3H:1V side slopes on the exterior. Based on plans provided to CDM, a 6-foot-thick clay core was constructed in the middle of the embankment. The depth of the clay core is unknown. As part of the construction, a diversion embankment was also constructed in the area of the current Pond A/C divider embankment.

From about 1981 to 1982, the east impoundment (Ponds D and E) was unofficially capped and regraded with 4H:1V side slopes to approximately elevation El. 627. The surface was mulched and seeded per the drawings reviewed by CDM.

In about 1991, the current configuration of Ponds A, B, and C was constructed. The embankment around the perimeter of Pond A was raised to crest elevation El. 629 using compacted ash. A typical cross-section of the embankment is presented in [Figure 3](#). Based on drawings provided to CDM, a 6-foot-thick clay core or slurry trench was installed in the middle of the embankment and was keyed a minimum of 2 feet into native soil. The embankment generally has a 10-foot-wide crest and 2H:1V side slopes on the interior and 3H:1V side slopes on the exterior. The current configuration and operation of Ponds A, B and C is discussed below.

In 2000, the east impoundment (Ponds D and E) was reactivated. The embankment around the pond was regraded from the toe up with 3H:1V side slopes, and the crest was raised to elevation El. 633 using compacted ash. The embankment crest was 20 feet wide and the interior slope was 3H:1V. In 2003, the current configuration of Pond D and E was created by constructing internal divider embankments and a diversion embankment. The modifications were constructed with a 20-foot-wide crest and 3H:1V side slopes using compacted ash. In 2005, the embankment around the perimeter of Pond D was raised to elevation El. 643 using compacted ash. A typical cross-section of the embankment is presented in [Figure 4](#). The embankment has a 20-foot-wide crest with 3H:1V side slopes.

In February 2007, the divider embankment between Ponds D and E failed causing the north and west embankment of Pond E to overtop. Subsequently, the north embankment breached due to the overtopping. Following the failure, Ponds D and E were repaired and brought back in service by December 2007. In January 2008, the divider embankment failed again in a similar manner to the first failure causing the north and west embankment of Pond E to overtop. Subsequently, the north embankment breached due to the overtopping. Ponds D and E are currently being repaired. The two failures, repair, and proposed configuration and operation of Ponds D and E are discussed below.

1.4.2 Current CCW Impoundment Configuration

The impoundments at the EV Generating Station currently are used as settling ponds for CCW waste and other plant wastes. CCW wastes sluiced into the impoundments include:

- Bottom ash;
- Fly ash;
- Boiler slag;
- Ash and & Pyrite system;
- Boiler blowdown; and

- Boiler, condenser, air-preheater, and cooling cleaning wastes.

Other plant wastes sluiced into the ash ponds include liquids from:

- Plant sumps;
- Flood drains;
- Stormwater runoff;
- Water treatment wastes;
- Metal cleaning wastes;
- River dredging; and
- Laboratory and sampling streams

There are currently five impoundments (Ponds A through E) at the EV Generating Station as shown on [Figure 5](#).

Currently the west impoundments consists of Pond A, Pond B, and Pond C. Pond A, Pond B, and Pond C are approximately 19, 13, and 8 acres in size, respectively. The crest elevation of the three impoundments is approximately El. 629, El. 619, and El. 619 respectively. The water levels in Pond A, Pond B, and Pond C are generally operated at a fixed elevation of approximately El. 626, El. 616, and El. 610, respectively.

Two (2) 10-inch-diameter High Density Polyethylene (HDPE) pipes sluice CCW waste into Pond A (Photo 6). In addition, a third 10-inch-diameter HDPE pipe sluices plant wastes into Pond A (Photo 10). Pond A is used as the primary settling pond. Floating booms were installed in the pond to direct flow and increase the settling time in the pond. Pond A is connected to Pond B by two (2) 30-inch-diameter Corrugated Metal (CMPs) with an invert elevation of El. 626 (Photo 28, 29 and 30). At the pipe inlets, there is a floating boom wrapped around the inlets and vertical pipe T's are connected to the ends to serve as a hood to reduce the potential for surface debris from clogging the pipes. IPL staff stated that a low spot in the crest in Pond A is an emergency overflow spillway (Photo 28). The spillway is approximately 50 feet wide with the crest at El. 628. This "emergency spillway" is not included on any design plans.

Pond B is used as a secondary pond for finer material to settle out. There are also floating booms installed in Pond B to increase the settling time in the pond prior to discharging into Pond C. Along the interior slope of the western embankment, floating booms consisting of telephone poles were installed to reduce wave action on embankment slopes. Pond B is connected to Pond C by two (2) 30-inch-diameter CMPs with an invert elevation of El. 616.

Pond C is used as a final settling pond before water is discharged into the discharge canal at outfall 001 (Photo 66). Water from Pond B and Pond E is conveyed to Pond C. A 24-inch-diameter pipeline carries flow from an inlet structure located in the northwest corner of Pond E to an outlet located in Pond C. Similar to Ponds A and B,

floating booms were installed in Pond C to increase the settling time in the pond prior to discharge. The booms consist of telephone poles that were installed along the interior slope of the west and north embankment to reduce wave action. Three telephone poles were also installed in front of the inlet structure in Pond C to reduce the potential for surface debris from entering the structure. The inlet structure in Pond C consists of a concrete box structure with stoplogs at the inlet to control flow (Photo 54). The inlet structure discharges into a 24-inch-diameter conduit. A butterfly valve located at the inlet structure catwalk can also be used to control flow. The butterfly valve appeared to be maintained and could be operated with little effort.

The east impoundments consist of Pond D and Pond E. Pond D and Pond E are approximately 16 and 4 acres in size, respectively. The crest elevation of the two impoundments is approximately El. 643 and El. 633, respectively. Currently Ponds D and E are dry and repairs are under construction. The proposed water level in Pond D after the repairs are completed is elevation El. 626. IPL has contractors filling Pond E with compacted ash but is not officially closing the pond under any state or federal regulations. The ash will be graded up from elevation El. 633 to El. 643, as shown in [Figure 4](#). The repair plans indicate that the compacted ash will be covered with a 12-inch-thick layer of compacted clay and a 4-inch-thick topsoil layer. A conduit consisting of 30-inch-diameter HDPE pipe with 8-foot-square anti-seep collars at 50-feet on center will be constructed through the compacted ash in Pond E to the existing inlet structure in the northwest corner of the pond. Water from Pond D will be diverted through the conduit to the inlet structure and into Pond C. IPL staff stated upon completion of the repairs, Pond D is anticipated be used on an “emergency” basis, i.e. when plant operating conditions make it absolutely necessary, or when Pond A and Pond B need to be taken offline for maintenance. A butterfly valve located at the inlet structure catwalk in Pond E can be used to control flow from Pond D to Pond C. The butterfly valve appeared to be maintained and could be operated with little effort.

1.4.3 Other Impoundments

No other impoundments were identified at the EV Generating Station.

1.5 Previously Identified Safety Issues

Based on our review of the information provided to CDM and as reported by EPA, there have been two identified impoundment-related safety issues at the EV Generating Station within the last 10 years. A summary of the two safety issues is discussed below.

1.5.1 February 14, 2007 Failure

On February 14, 2007, the north divider embankment between Pond D and Pond E failed. No documentation of this failure was available for review. Based on the Causal Analysis report prepared by BT², dated October 15, 2008, the water level in Pond D

was probably at the invert of the outlet pipes (El. 639.5) that were constructed through divider embankment D/E. BT² reported that the failure appeared to occur at the eastern reach of divider embankment D/E resulting in a semi-circular bowl shaped feature. The failure formed at the north toe of the north divider embankment D/E and extended east towards the intersection with the western divider embankment D/E and Pond D diversion embankment. Failure of the north divider embankment D/E caused the north and west embankment of Pond E to be overtopped. Subsequently, the north embankment of Pond E breached resulting in an uncontrolled release of 30 million gallons of water into the discharge canal. BT² attributed the failure of divider embankment D/E to slope instability combined with piping erosion of the flyash at the north toe of divider embankment D/E.

1.5.2 January 30, 2008 Failure

IPL began repairs and reconstruction of the north divider embankment D/E and the north embankment of Pond E in the summer of 2007. Construction was completed by November 2007, and the facility was put back in service. Pond D was filled with water to elevation El. 639.5 by the end of December 2007, and flow of water through the outlet pipes into Pond E began to occur. On January 30, 2008, the north divider embankment D/E failed for a second time. The failure of the north divider embankment D/E caused the north and west embankments of Pond E to be overtopped. Subsequently, the north embankment of Pond E breached resulting in a second uncontrolled release of 30 million gallons of water into the discharge canal. BT² attributed the second failure to the repair designed by Fuller, Mossbarger, Scott, and May Engineers (FMSM) in that they overestimated the shear strength of the flyash. BT² concluded the redesigned embankment cross-section by FMSM was inadequate to support the loading conditions in Pond D and Pond E.

BT² designed the second remedial design in 2008. The construction is currently ongoing. Construction is anticipated to be completed in the summer of 2010.

1.6 Site Geology

The site is located south of the White River. The area north of the discharge canal and the west impoundments are located within the 100 year floodplain. The ground surface around the impoundments ranges from approximately El. 605 to El. 613. Based on a review of available subsurface information and reports, the site is located within a glacial valley created by the erosion of the bedrock hills and the deposition of sand and gravel by glaciers and by the White River and Indian Creek. The subsurface conditions at the site generally consist of 1 to 14 feet of lean clay underlain by deposits of sand and gravel with variable amounts of clay down to bedrock. The bedrock in the vicinity of the site consists of soft shale at anticipated depths of approximately 100 to 120 feet below natural grade.

Section 2

Field Assessment

2.1 Visual Observations

CDM performed a visual assessment of the CCW impoundments at the EV Generating Station. The perimeter embankments of the impoundments total approximately 9,630 feet in length and are up to 38 feet high. The assessments were completed following the general procedures and considerations contained in Federal Emergency Management Agency's (FEMA's) Federal Guidelines for Dam Safety (April 2004) relative to observations concerning settlement, movement, erosion, seepage, leakage, cracking, and deterioration. A Coal Combustion Dam Inspection Checklist and CCW Impoundment Inspection Form, developed by USEPA, were completed on-site for each impoundment during the site visit. Copies of these forms are included in [Appendix A](#). Photograph location plans are shown on [Figures 6a and 6b](#), and photographs are included in [Appendix B](#).

It should be noted tall vegetation in areas obscured visual observations of the exterior embankments. In particular, this is the case on the east and south exterior slope of Pond A and around the perimeter of Pond D and Pond E.

CDM visited the site on April 28 and April 29, 2010 to complete visual assessments of the impoundments. The weather was generally sunny with temperatures between approximately 60 and 75 degrees Fahrenheit. The daily total precipitation prior to the site visit is shown in [Table 1](#).

Table 1 - Approximate Daily Total Precipitation Prior to Site Visit

Dates of Site Visits - April 28, 2010 & April 29, 2010		
Day	Date	Precipitation (inches)
Wednesday	April 21	0
Thursday	April 22	0
Friday	April 23	0
Saturday	April 24	0.08
Sunday	April 25	0.45
Monday	April 26	0.62
Tuesday	April 27	0
Wednesday	April 28	0
Thursday	April 29	0
Total	Week Prior to Site Visit	1.15
Total	Month Prior to Site Visit	3.26

Notes:

1. Precipitation data from www.weather.com.

2.2 Pond A

2.2.1 Exterior Slope

The exterior slopes of the Pond A embankments appear to be in fair condition. The exterior slopes on the north, south, east, and west embankments ranged from approximately 2.5H:1V to 3H:1V (Photos 1, 15, 20, 23, 25, 45, and 46). The exterior slope on the embankment between Pond A and Pond B (divider embankment A/B) and embankment between Pond A and Pond C (divider embankment A/C) ranged from approximately 2H:1V to 3H:1V (Photos 28, 33, 34, 38, 40, and 42).

The north, south, east, and west embankments were generally covered with grassy vegetation approximately 12 to 48 inches tall. There are multiple species of grass growing on the slope from the various expansions and erosion repairs. There was some small brush on the southwest embankment (Photo 23) and one bush growing on the east embankment.

On the east embankment there are some areas of sparse vegetation near the crest where the topsoil has a significant amount of gravel. There was also some minor surface erosion observed around the perimeter embankments.

One erosion repair on the northeast corner of the east embankment was observed (Photos 1, 3, and 4). The repair consists of an erosion control blanket. The erosion control blanket did not appear to be installed consistent with typical manufacturer's recommendations. Stakes did not appear to be installed properly, and the blankets were not overlapped or keyed into an anchor trench in the slope. Approximately 1- to 3-inch gaps were observed below the blanket. Another erosion rill was observed on the west embankment (Photo 26). Some crushed stone was placed near the crest of the embankment in an effort to reduce further erosion.

There were two low spots at the toe of the east embankment (Photo 5). At the low spots, there was also some minor sloughing. IPL stated these were low areas where a tractor had previously gotten stuck during mowing operations. A surface depression was also observed near the crest of the eastern embankment (Photo 7).

A possible former seep area was observed at the toe of the east embankment (Photo 12). A possible former seep was also observed in a soft spongy area along the toe of the south embankment (Photo 21). No active seepage was observed during the site visit. However, active seepage in these areas has been noted in previous inspection reports.

The exterior slopes on the divider embankments A/B and A/C were generally protected with riprap or crushed stone armor. Some areas were not armored and were covered with vegetative protection. Some erosion features, surface depressions, and minor sloughing were observed on the slope (Photos 32, 35, 36, 37, and 38). Some of the larger surface erosion areas appeared to have been recently filled with riprap or

stone (Photos 38, 40, 41, and 42). There was also some brush and small trees growing at the toe of the divider embankment in Pond C (Photo 42).

2.2.2 Crest

The crest of the Pond A embankments appeared to generally be in fair condition (Photos 2, 8, 14, 16, 19, 22, 24, 27, 30, 34, 43, and 44). The crest was approximately 15 feet wide with exception of the truck turn around area where the crest was significantly wider. The crest consists of a compacted gravel access road around the perimeter. Three low spots were observed in the crest (Photos 2, 14, and 28). Two of the low spots appear to be from recent truck traffic rutting the crest. The low spot on the east embankment observed on 4/28/10 was filled in by IPL personnel by 4/29/10. IPL indicated that the low spot on the divider embankment near the outlet pipes (Photo 28) is an overflow spillway. There are no records in the information provided to CDM to indicate this was a design feature. There were no deficiencies observed in this area.

2.2.3 Interior Slope

The interior slope of the Pond A embankments was not visible along the north and east and majority of the west embankment due the presence of ash. The interior visible portion of the slope appeared to be generally armored with a layer of crushed stone and 3- to 4-inch stone. The visible portions of the interior slope were approximately 2H:1V. A heavier riprap layer is present around the outlet pipes (Photo 29).

2.2.4 Outlet Pipes

The outlet pipes in Pond A were in fair condition (Photos 28, 29, and 30). The T-connections at the inlets appear to be settling downward in most instances. The coupling at the connection between the T and the pipe may be starting to buckle from supporting the weight of the T based on observed sagging of the connection. The inlets were clean and a floating boom was wrapped around the inlets to reduce the potential for debris to clog the pipes.

2.3 Pond B

2.3.1 Exterior Slope

The exterior slopes of the Pond B embankments appear to be in fair condition. The exterior slopes on the north and west embankments ranged from approximately 2.5H:1V to 3H:1V (Photos 59, 61 and 64).

The west embankment was generally covered with a grass approximately 12 to 48 inches tall. Riprap was recently placed on the exterior slope based on previous inspection reports and IPL personnel.

An erosion rill on the exterior slope at the southern reach of the west embankment was observed (Photo 65). The erosion rill had recently been filled with riprap to reduce further erosion.

2.3.2 Crest

The crest of the Pond B embankments appeared to be generally in fair condition (Photos 31, 39, 57, 60 and 63). The crest was generally approximately 15 feet wide. The crest consists of a compacted gravel access road around the perimeter.

2.3.3 Interior Slope

The interior slope of the Pond B embankments appeared to be generally in fair condition (Photos 31, 39, 58, 60 and 62). The interior slopes were approximately 2H:1V. Riprap was recently placed on the interior slope to repair significant erosion that had occurred based on information contained in previous inspection reports and discussions with IPL personnel. The extent of the erosion before placement of the riprap is unknown. Floating telephone poles that were previously used as the primary protection against wave action are still installed along the west embankment.

2.3.4 Outlet Pipes

The outlet pipes in Pond B were in fair condition (Photos 57, 58, and 59). The west outlet pipe is slightly lower than the east outlet pipe. No unusual movement was observed around the pipe penetrations.

2.4 Pond C

2.4.1 Exterior Slope

The exterior slopes of the Pond C embankments appear to be in fair condition. The exterior slopes on the north and west embankments were approximately 3H:1V (Photos 46, 50 and 53). The embankment was generally covered with grass approximately 12 to 48 inches tall. No erosion or other deficiencies were observed on the north and west embankments during the site visit.

2.4.2 Crest

The crest of the Pond C embankments appeared to be generally in fair condition (Photos 48, 52, and 56). The crest was generally approximately 15 feet wide. The crest consists of a compacted gravel access road around the perimeter.

2.4.3 Interior Slope

The interior slope of the Pond C embankments appeared to be generally in fair condition (Photos 47, 49, 51, and 54). The interior slopes were approximately 2H:1V. Most of the north embankment has no erosion protection or armor. There is some riprap on the north embankment near the northeast corner and at the outlet structure. On the north embankment in the northeast corner there is an erosion rill developing

(Photo 47). Fill and riprap was recently placed around outlet structure in the northwest corner (Photo 54) per previous inspection reports and IPL personnel.

On the west embankment there are large segments without erosion protection or armor. Eroded areas on the west embankment have been repaired with crushed stone and 3- to 4-inch stone. An erosion feature from the diversion boom rope was observed on the west embankment (Photo 55).

2.4.4 Outlet Structure

The outlet structure in Pond C was in fair condition (Photos 54 and 66). The inlet was free of debris, and water was flowing through the trash rack. The butterfly valve on the catwalk appeared to be maintained and could be turned with little effort. The outfall in the discharge canal appeared to be in fair condition. There was no visible erosion, and the pipe was not clogged.

2.5 Pond D

2.5.1 Exterior Slope

The exterior slopes of the Pond D embankments appear to be in fair condition with exception of the breached area. The exterior slopes on the north, south, east, and west embankments were approximately 3H:1V (Photos 67, 74, 75, 76, 83, 86, 89, 91, 97, 98, 131, 134, 135, 137, 143, 144, 145, and 146). The exterior slope on the embankment between Pond D and Pond E (divider embankment D/E) was approximately 3.5H:1V on the north embankment (Photos 99, 103, and 124) and approximately 3H:1V on the west embankment (Photos 122 and 125).

The north, south, east, and west embankment slopes were generally covered with grassy vegetation. The vegetation was approximately 12 to 48 inches tall. There are multiple species of grass growing on the slope from the various expansions and erosion repairs. Generally there are three distinct bands from the expansions (Photo 9). The vegetation on the upper third of the slope generally was shorter, and there were multiple areas of sparse vegetation (Photos 80, 81, 84, 85, 89, 97, 122, and 125). The topsoil layer on the upper third of the slope had a significant amount of sand and gravel and was loose in nature. Multiple surficial erosion features were observed on the upper portion of the embankment around the perimeter of the impoundment (Photos 72, 73, 82, and 90). A riprap layer was observed at approximately El. 625, consistent with the first crest elevation. The riprap layer was observed on the east, south, and west perimeter embankments.

The upper portion of the north and west divider embankment D/E had a vegetative cover. On the north divider embankment at approximately El. 630 there was a 19-foot-wide by 5-foot-high buttress berm. The buttress berm was covered with riprap over a filter fabric (Photo 99 and 103). Washout from the breach and excavated material from the repair work was observed on the riprap.

2.5.2 Crest

The crest of the Pond D embankments appeared to be generally in fair condition (Photos 68, 69, 77, 84, 87, 92, 100, 121, 132, 138, and 142). The crest was generally approximately 20 feet wide. The crest consists of a compacted gravel access road around the perimeter. Some tire rutting was observed from the recent truck traffic.

Five piezometers were installed on the crest of Pond D by BT² between June 11, 2008 and June 13, 2008. The well covers for three of the piezometers were observed (Photo 78).

2.5.3 Interior Slope

The interior slope of the Pond D embankments appeared to be generally in fair condition with exception of the breached area (Photos 69, 79, 88, 92, 93, 94, 95, 96, 101, 139, and 141). The interior slope generally was 3H:1V slope where visible. Slope armor on the north, east, and south embankment appeared to be a layer of crushed stone and/or shale. The interior slope on divider embankment D/E was armored with riprap over a filter fabric on approximately the upper 6 feet.

Some erosion rills were observed on the interior slope of divider embankment D/E (Photo 93 and 94).

2.5.4 Diversion Embankment

The diversion embankment appeared to be in fair condition. The crest consisted of an approximately 20-foot-wide crushed stone access road with weeds growing at the end of the embankment (Photos 129). The east and west slope of the embankment was generally 3H:1V. Riprap was observed on approximately the upper six feet (Photos 95 and 102) of the embankment. Two erosion features were observed on the diversion embankment (Photos 126 and 127). A surface depression with potential minor piping activity was observed at the crest on the east slope (Photo 130).

2.5.5 Breached Section and Remedial Construction

The remedial construction of the breached portion of divider embankment D/E was observed during the site visit. The breached section has been cut back at approximately a 3H:1V slope (Photos 94, 102, 118, 122, and 124). The outlet pipes from the divider embankment were observed (Photo 125). The pipes appear to be in satisfactory condition. The replacement piping and anti-seepage collars for the repair work were also observed (Photo 71). Portions of the concrete anti-seepage collar from the 2007 repair were also observed on the crest of divider embankment D/E (Photo 118). The remaining sections of the embankment appeared to be in fair condition.

2.5.6 Toe Drain

A toe drain along the north embankment exterior toe was observed during the site visit (Photo 134). The toe drain discharges into a sump pit located northeast of Pond D (Photo 70). The outlet was underwater and no flow was observed from the toe drain.

2.6 Pond E

2.6.1 Exterior Slope

The exterior slopes of the Pond E embankments appear to be in poor condition. The exterior slopes on the north and west embankments were approximately 3H:1V (Photos 105, 111 and 114). The embankment was generally covered with a grass approximately 12 to 48 inches tall. There were significant erosion features on the west and north embankment exterior slope from the overtopping on January 30, 2008 (Photos 106, 107, 112, 113, and 119).

2.6.2 Crest

The crest of the Pond E embankments appeared to be generally in fair condition (Photos 110, 116, and 120). The crest was generally approximately 20 feet wide. The crest consists of a compacted gravel access road around the perimeter.

2.6.3 Interior Slope

The interior slope of the Pond E embankments appeared to be generally in fair condition with exception to the breach area (Photos 103, 104, 109, 116, and 120). The interior slopes were approximately 3H:1V. Approximately the top 6 feet of the interior slope had erosion protection consisting of riprap. Compacted ash was being backfilled against the interior slope as part of the repair work (Photos 103, 104, 116, 117, and 120).

2.6.4 Breached Section and Remedial Construction

The remedial construction of the breached portion of the north embankment was observed during the site visit. The breached section has been cut back at approximately a 3H:1V slope (Photos 104, 114, 116, 117, 118, 120). Ash was being excavated from Pond A (Photos 8, 11, and 16) and was being placed as compacted fill. Five tri-axle dump trucks were transporting the ash from Pond A to Pond E. A Caterpillar B85 track dozer was being used to spread the ash and a Caterpillar vibratory soil compactor was being used to compact the lifts of ash. A field representative from BT² was onsite to perform field density and moisture content testing of the compacted ash backfill.

2.6.5 Outlet Structure

The outlet structure in Pond E was in fair condition (Photos 104 and 115). The inlet was free of debris and stoplogs were in place. The butterfly valve on the catwalk appeared to be maintained and could be turned with little effort. The discharge pipeline manholes from Pond E to Pond C appeared to be in fair condition (Photo 108). Water was not coming out of the outlet in Pond C.

DRAFT

Section 3

Data Evaluation

3.1 Design Assumptions

CDM was not provided with any of the original IPL design assumptions for the CCW impoundments. IPL provided some design documents related to the first and second repairs of Pond D and Pond E. CDM has reviewed the available information related to the design and analysis of Ponds D and E. The design assumptions are discussed in the following sections.

3.2 Hydrologic and Hydraulic Design

CDM was not provided with any hydrologic and hydraulic designs and analyses for the five impoundments.

CDM performed a preliminary evaluation of the hydraulic capacity of the impoundments to estimate if the ponds are adequately sized to store or pass the design storm event. Based on “General Guidelines for New Dams and Improvements to Existing Dams in Indiana”, IDNR (February 2010), the Probable Maximum Precipitation (PMP) for a 6-hour storm event over a 10 square-mile area in the vicinity of the site is approximately 27.3 inches. IDNR requires significant and high hazard structures to pass 50% PMP and 100% PMP, respectively. The drainage area contributing to the ponds at this site is limited to the storage area within the impoundments. Preliminary evaluations indicate that there is enough storage capacity and freeboard in Ponds A, B, C, and E at the current operating pools to safely store a 50% PMP event without being overtopped. Preliminary evaluation of Pond D indicates that there is enough storage capacity and freeboard at the current operating pool to safely store a PMP event without being overtopped.

3.3 Structural Adequacy & Stability

The IDNR requires new and existing structures be evaluated under standard design guidelines. Procedures established by the United States Army Corps of Engineers (USACE), the United States Bureau of Reclamation, the Federal Energy Regulatory Commission, and the United States Natural Resources Conservation Service are generally accepted engineering practice. Minimum required factors of safety outlined by the USACE in EM 1110-2-1902, Table 3-1 and seismic factors of safety by FEMA Federal Guidelines for Dam Safety, Earthquake Analyses and Design of Dams (pgs. 31, 32 and 38, May 2005) are provided in [Table 2](#).

Table 2 - Minimum Safety Factors Required

Load Case	Minimum Required Factor of Safety
Steady-State Condition at Normal Pool or Maximum Storage Pool Elevation	1.5
Rapid Drawdown Condition from Normal Pool Elevation	1.2
Maximum Surcharge Pool (Flood) Condition	1.4
Seismic Condition from at Normal Pool Elevation	1.0
Liquefaction	1.3

3.3.1 Pond A, Pond B & Pond C

CDM was not provided with any information regarding the structural adequacy and stability of Ponds A, B, and C. CDM was not able to perform stability analyses for the embankments because CDM was not provided with any information relative to the properties of the foundation and embankment materials.

3.3.2 Pond D & Pond E

After the first failure in 2007, IPL retained BBCM Engineers to evaluate the embankments. BBCM performed four test borings in the vicinity of the breach in February 2007. IPL later retained FMSM. FMSM performed five additional borings in the vicinity of the breach in May 2007. FMSM performed laboratory testing on representative samples recovered from the test borings. Laboratory testing included:

- Moisture Content;
- Sieve and Hydrometer Analysis;
- Atterberg Limits;
- Standard Proctor Moisture-Density Tests;
- Unconfined Compressive Strength Tests; and
- Consolidated Undrained Triaxial Shear Strength Tests.

FMSM performed slope stability analyses to evaluate the stability of the existing embankment in the vicinity of the failures and proposed repairs. A summary of the soil parameters used in the analyses is presented in [Table 3](#) below. FMSM evaluated the stability of divider embankment D/E under long-term normal pool and rapid drawdown conditions. Based on FMSM's analyses the factor of safety (FS) against slope failure for the existing embankment cross-section was 1.0 and 0.8 for long-term normal pool and rapid drawdown conditions, respectively. FMSM also evaluated the stability of embankment repairs. FMSM proposed a repair consisting of a 5-foot-thick granular buttress berm with a bench at El. 630, as shown on [Figure 7](#). Based on FMSM's analyses, the FS against slope failure for the repaired embankment cross-

section was 1.5 and 1.4 for long-term normal pool and rapid drawdown conditions, respectively. No other stability analyses were performed for the impoundment.

Table 3 – FMSM – Pond D & E Soil Parameters

Stratum	Unit Weight (pcf)	Friction Angle (°)	Cohesion (psf)
Flyash	90	33	--
Clay	125	25	50
Sand and Gravel	120	31	--

After the second failure in 2008, IPL retained BT², Inc., to investigate the cause for the two failures in Ponds D and E. BT² performed seven additional borings around the impoundments in June 2008. BT² performed laboratory testing on representative samples recovered from the test borings. Laboratory testing included:

- Moisture Content;
- Sieve and Hydrometer Analysis;
- Atterberg Limits; and
- Hydraulic Conductivity.

BT² performed slope stability analyses to evaluate the stability of the original cross section, FMSM's remedial design, and proposed repairs. BT² first back calculated the shear strength of the flyash using FMSM's design to obtain a FS=1.0. A summary of the soil parameters used in the analyses are presented in [Table 4](#) below. After estimating the shear strength of the flyash, BT² evaluated the stability of divider embankment D/E under long-term normal pool conditions. Based on BT²'s analyses, the FS against slope failure for the FMSM embankment repair was 0.91 to 0.96. BT² evaluated multiple remedial improvements under long-term normal pool elevation. Based on BT²'s analyses, the FS against slope failure for their conceptual embankment improvement, shown on [Figure 8](#), was 1.95. BT² also evaluated the stability of Pond E's north embankment. Based on BT²'s analysis, the FS against slope failure was 0.87. In addition, BT² evaluated the stability of the Pond E embankment with a lower water level at El. 620 and a buttress berm on the exterior slope. Based on BT²'s analysis the long-term FS against slope failure was FS=1.57. No other stability analyses were performed for Pond D or Pond E.

Table 4 – BT² – Pond D & E Soil Parameters

Stratum	Unit Weight (pcf)	Friction Angle (°)	Cohesion (psf)
Flyash	90	21	--
Clay	125	25	50
Sand and Gravel	120	31	--
Toe Drain	140	35	--

3.4 Foundation Conditions

CDM was not provided with information to evaluate if Pond A, Pond B or Pond C were constructed on wet ash, slag or other unsuitable materials.

Documents reviewed by CDM indicate that Pond D and Pond E embankments appear to have been constructed on moist to wet, very soft to soft flyash with moisture content ranging 11.2% to 79%. In general, it appears that below the flyash soft to stiff, lean clay underlain by medium dense sand and gravel with variable amounts of clay was present. Shale bedrock is anticipated at depths of approximately 100 to 120 feet based on our review of the literature. The moisture content of two clay samples at test borings B-5 and B-6 were at or greater than the liquid limit.

CDM was not provided with documentation of foundation preparation for the vertical expansions of pond D and Pond E. However organics, concrete, wood, and silty clay were encountered in the test borings performed by BT², which may have been present at the foundation of the vertical expansions.

3.5 Operations & Maintenance

IPL personnel indicated that there is no written formal operation or maintenance program. They also do not have an emergency action plan. Routine maintenance performed includes mowing grass on embankment slopes once per year, and other activities as needed to address other observed conditions such as erosion and revegetation. IPL personnel also indicated water levels are not monitored in the impoundments.

In addition, EV Generating Station personnel perform visual inspections of the impoundments every two weeks. Plant personnel were trained by BT² to perform the visual inspections. A copy of the typical inspection checklist is provided in [Figure 9](#). As issues are observed, work orders are placed at the plant for identified deficiencies to be repaired. Additional observations are completed after significant storm events. These additional observations are not documented. Since 2008, semi-annual detailed visual inspections have also performed at the EV Generating Station by BT². Inspection reports, with conclusions and recommendations, are prepared and submitted to IPL.

Section 4

Conclusions/Recommendations

4.1 Hazard Classification

The EV Generating Station impoundments currently do not have an IDNR- developed Hazard Potential Classification. Based on the USEPA classification system as presented on page 2 of the USEPA check list ([Appendix A](#)) and our review of the site and downstream areas, recommended hazard ratings have been assigned to the impoundments as summarized in [Table 5](#) below:

Table 5 – Recommended Impoundment Hazard Classification Ratings

Impoundment	Recommended Hazard Rating	Basis
Pond A	Significant Hazard	<ul style="list-style-type: none"> • A breach could damage the railroad. • A breach could damage a transmission tower. • A breach could result in the failure of Pond B or Pond C. • A breach would have an environmental impact on the White River, Discharge Canal, and downstream area.
Pond B	Significant Hazard	<ul style="list-style-type: none"> • A breach could result in the failure of Pond A or Pond C. • A breach would have an environmental impact on the White River, Discharge Canal, and downstream area.
Pond C	Significant Hazard	<ul style="list-style-type: none"> • A breach could result in the failure of Pond A or Pond B. • A breach would have an environmental impact on the White River, Discharge Canal, and downstream area.
Pond D	High Hazard	<ul style="list-style-type: none"> • A breach could result in the failure of Pond E. • A breach would have an environmental impact on the White River, Discharge Canal, and downstream area. • A breach could damage a transmission tower. • A breach could damage the railroad. • A breach or misoperation could cause loss of life at the plant.
Pond E	Significant Hazard	<ul style="list-style-type: none"> • A breach could result in the failure of Pond D. • A breach would have an environmental impact on the White River, Discharge Canal, and downstream area. • A breach could damage the railroad.

4.2 Acknowledgement of CCW Impoundment Condition

CDM acknowledges that the management units (Pond A, Pond B, Pond C, Pond D, and Pond E) referenced herein were assessed by Michael L. Schumaker, P.E. and Michael P. Smith. Ponds A, B, and C appeared to be in fair condition based on site observations. However, there is a lack of documentation relative to the design and construction of these facilities. It is not known if critical studies or investigations (stability, hydrologic, hydraulic, seismic) have been performed to confirm that potential safety deficiencies do not exist. Therefore, Ponds A, B, and C are judged to be in **POOR** condition. Additional documentation and future studies performed to confirm the condition and performance of these impoundments may be sufficient to substantiate an improved condition assessment. Ponds D and E were also judged to be in **POOR** condition. An assessment of POOR for these ponds is due to incomplete breach repairs and the need for additional studies or investigations to confirm that other potential safety deficiencies do not exist.

As described in the following sections, further studies, maintenance and monitoring may further improve the condition of these impoundments.

4.3 Maintaining and Controlling Vegetation Growth

Tall vegetation in areas obscured visual observations of the exterior embankments. In particular, this is the case on the east and south exterior slope of Pond A and around the perimeter of Pond D and Pond E. There was also some brush and small trees growing at the toe of the Pond A divider embankment in Pond C. On impoundments with either standing water or high piezometric levels within the deposited ash, tree roots can concentrate seepage of water through the embankments, which could lead to internal erosion. Internal erosion would weaken the embankment, reduce stability, and could result in a slope failure and potential release of stored water and ash.

CDM recommends that vegetation be cut on a regular basis to ensure that adequate visual observations can be made by IPL's personnel during routine inspections and by the independent consultant during their semi-annual inspection.

4.4 Erosion Protection and Repair

Erosion rills and loss of ground cover were observed on multiple embankment slopes of Ponds A through E as discussed in [Section 2](#). Thinning and loss of grass cover due to concentrated flow was noted on some embankment slopes. CDM recommends filling all rills and re-seeding these areas. Large erosion features were noted on the west exterior slope of Pond E from the 2008 overtopping. The erosion features are scheduled to be backfilled as part of the remedial work.

4.5 Impoundment Hydraulic and Stability Analysis

IPL did not provide CDM with a hydraulic analysis showing the ability of the impoundments to safely pass the 50% or 100% PMP event. However, a preliminary evaluation performed by CDM suggests there is enough storage capacity at the current operating pool levels to safely store precipitation from this rainfall event. CDM recommends IPL perform a complete study to confirm this conclusion, and update the study if operating levels of the pond change in the future.

CDM was not provided with information regarding stability analyses performed prior to or following construction of Pond A, Pond B, or Pond C or information regarding properties of the embankment and foundation materials. It is recommended that detailed stability analyses be performed for Pond A, Pond B, and Pond C embankments. The stability analyses for each pond should include a subsurface investigation to evaluate existing soil parameters in the embankments and foundation soils and the installation of piezometers to measure the current phreatic surface. Stability analyses should consider all appropriate operating and loading conditions including rapid drawdown if applicable, and seismic events.

BT² performed stability analyses for Pond D and Pond E which indicated that the embankment was marginally stable and remedial work was required. The stability analyses did not consider other potential critical cross-sections, such as the south embankment or loading conditions for maximum surcharge pool (flood), seismic or rapid drawdown conditions. CDM recommends that other critical cross-sections and loading conditions be evaluated relative to slope stability for these impoundments.

CDM recommends that all analyses be performed by a registered professional engineer experienced in earthen dam design.

4.6 Remedial Design

The remedial design by BT² includes the installation of a 30-inch-diameter HDPE pipe with 8-foot square HDPE anti-seep collars at 50-feet on center through the compacted ash in Pond E. CDM recommends that the use of filter diaphragms be considered to control potential seepage along pipes in lieu of anti-seep collars. This is due to potential construction difficulties associated with proper placement and compaction of fill materials in the vicinity of the anti-seep collars, which can render the collars ineffective.

4.7 Inspection Recommendations

Based on the information reviewed by CDM it does not appear that IPL has adequate inspection practices. Currently inspection documentation prepared by plant personnel consist of limited checklists completed every two weeks for all five ponds to document the presence of any failures, erosion, vegetative cover in a "yes" or "no" format and to document operation conditions such as work activities. The inspection

checklists are inadequate to document specific potential items that need to be addressed and the area where they are located. CDM recommends that plant personnel develop more-detailed inspection documentation procedures to aid in ensuring that they are performing adequate inspections and adequately documenting observations over time. Documentation should include a sketch of relevant features observed, and the documentation should be periodically reviewed to identify if conditions are worsening and/or if significant changes are occurring which could lead to additional maintenance issues or safety concerns.

Inspection procedures should include the recording of data from existing piezometers on Pond D and Pond E. A staff gage should be installed at outlet structures to record water levels in the impoundments, if applicable. In addition, inspections should be made following heavy rainfall and/or high water events on the White River, and the occurrence of these events should be documented. It is recommended that inspection records be retained at the facility for a minimum of three years.

DRAFT

Section 5

Closing

The information presented in this report is based on visual field observations and review of reports and data provided to CDM by IPL for the Eagle Valley Generating Station surface impoundments. The conclusions and recommendations presented are based, in part, on limited information available at the time of this report. This report has been prepared in accordance with generally accepted engineering practices. No other warranty, expressed or implied, is made. Should additional information become available or changes in field conditions occur, the conclusions and recommendations provided in this report should be re-evaluated by a qualified professional engineer.

DRAFT

Section 6

Reports and References

The following is a list of reports and drawings that were provided by Indianapolis Power and Light Company and were utilized during the preparation of this report and the development of the conclusions and recommendations presented herein.


1. Drawing No. 007-00-6-a-d-16b, "General Plan, Sheet No. 1, Units No. 1 & 2", prepared by Gibbs & Hill, Inc., March 7, 1947
2. Drawing No. 007-00-6-a-d-16a, "General Plot Plan", prepared by Indianapolis Power and Light Company, September 23, 1953
3. Drawing No. 007-00-6-y-d-g42, "New Ash Disposal Area Miscellaneous Details", prepared by Indianapolis Power and Light Company, May 5, 1981
4. Drawing No. 007-00-6-y-d-42J, "Abandon Ash Pond & New Decant Structure Area Plan", prepared by Indianapolis Power and Light Company, April 8, 1982
5. Drawing No. 007-00-6-y-d-42a, "Revised Ash Disposal Area", prepared by Indianapolis Power and Light Company, May 5, 1981, Revised May 1990
6. USGS Martinsville Quadrangle, prepared by USGS, 1998
7. Drawing, "Pond "D"", prepared by Indianapolis Power and Light Company, 2002
8. Drawing No. 006-00-6-y-d-xx, "Pond D Levee Additions", prepared by Indianapolis Power and Light Company, September 7, 2004
9. Drawing Sheet 1 of 1, "Eagle Valley Plant Ash Pond Final Asbuilt", Trans Ash, May 24, 2005
10. Plans for Construction, Remedial Drawings - 1st Repair, prepared by FSMS Engineers, August 10, 2007
11. 2008 Dike Inspection, prepared by Geosyntec Consultants, September 5, 2008
12. Causal Analysis Report - Eagle Valley Generating Plant, prepared by BT², October, 2008
13. Feasibility Analysis for Use of D-Pond for Future Processing of Ash Slurry, prepared by BT², December 18, 2008
14. Response to U.S. EPA 104(e) Information Request, prepared by Indianapolis Power & Light Company, May 13, 2009

15. Eagle Valley Generating Station Site Plan, prepared by Keramida, July 9, 2009
16. 2009 Dike Inspection, prepared by BT², August 7, 2009
17. Plans for Construction, Remedial Drawings – 2nd Repair, prepared by BT², September 24, 2009
18. 2009-2 Dike Inspection – Eagle Valley Generating Station, prepared by BT², April 5, 2010
19. Bi-Weekly Ash Pond Inspections Record, prepared by BT², from January 12, 2009, to April 19, 2010
20. Visual Inspections of Ash Pond Levees, prepared by Indianapolis Power & Light, from August, 2007, to March, 2010
21. General Guidelines for New Dams and Improvements to Existing Dams in Indiana, IDNR, February 2010

DRAFT

DRAFT

Figures



USGS TOPOGRAPHIC MAPS
MARTINSVILLE QUADRANGLE MAP
CONTOURS AND ELEVATIONS IN FEET


CDM

consulting • engineering • construction • operations

CITY OF MARTINSVILLE, INDIANA
EAGLE VALLEY GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY

LOCUS PLAN
MAY 2010

FIGURE 1



AERIAL PHOTOGRAPH SOURCE:
GOOGLE EARTH PRO.


CITY OF MARTINSVILLE, INDIANA
EAGLE VALLEY GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY

CDM


consulting • engineering • construction • operations

CRITICAL INFRASTRUCTURE MAP
MAY 2010


FIGURE 2



A. TYPICAL PERIMETER EMBANKMENT 1949




B. TYPICAL PERIMETER EMBANKMENT 1991



C. TYPICAL DIVIDER EMBANKMENT BETWEEN POND A AND POND B & C

NOTES:

1. TYPICAL CROSS-SECTION A FROM IPL DRAWING 007-00-6-A-D-16B.
2. TYPICAL CROSS-SECTION B FROM IPL DRAWING 007-00-6-Y-D-42G
3. TYPICAL CROSS-SECTION C FROM DRAWING 007-00-6-Y-D-42A



AERIAL PHOTOGRAPH SOURCE:
GOOGLE EARTH PRO.




consulting • engineering • construction • operations

CITY OF MARTINSVILLE, INDIANA
EAGLE VALLEY GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY

AERIAL MAP
MAY 2010

PW: \\comxmsvr01\pw_xmi\Documents\51119\76658_Eagle_Valley\03 Reports and Studies\09 CADD Figures and Graphics\TPLEGO06a.dwg



LEGEND:

 PHOTOGRAPH NUMBER AND ORIENTATION

NOTES:

1. BASE PLAN DEVELOPED FROM JULY 9, 2009 DRAWING PREPARED BY KERAMIDA



consulting • engineering • construction • operations

EAGLE VALLEY GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY
MARTINSVILLE, INDIANA


PHOTOGRAPH LOCATION PLAN

FIGURE 6a

2 PHOTOGRAPH NUMBER
AND ORIENTATION

1. BASE PLAN DEVELOPED FROM
JULY 9, 2009 DRAWING PREPARED
BY KERAMIDA

FIGURE 6b



NOTES:


1. STABILITY ANALYSIS FROM BT², CAUSAL ANALYSIS REPORT, OCTOBER 15, 2008.

EAGLE VALLEY GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY
MARTINSVILLE, INDIANA
DIVIDER EMBANKMENT D/E SLOPE STABILITY
ANALYSES PERFORMED BY FSM





consulting • engineering • construction • operations


FIGURE 7



A. MODIFIED DIVIDER EMBARKMENT D/E



B. POND E - NORTH EMBARKMENT



NOTES:

1. STABILITY ANALYSIS FROM BT², CAUSAL ANALYSIS REPORT, OCTOBER 15, 2008.

EAGLE VALLEY GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY
MARTINSVILLE, INDIANA

BT² SLOPE STABILITY ANALYSES
MAY 2010

CDM

consulting • engineering • construction • operations

FIGURE 8

DATE: 4-19-10

Ash Pond Description (Name/ID)	Date	Erosion Along Crest or Embankment Slopes (Y/N)	Appearance of Sinkholes or Failure (Y/N)	Tension Cracks Along Crest or Slope Faces (Y/N)	Presence of Vegetation Cover Along the Embankment Slopes (Y/N)	Changes in Dike Alignment (Y/N)	Appearance of Erosion/Deterioration Around Outlet Structures (Y/N)	Description of Current Operational Conditions (Normal/ Abnormal)	Initials	
									Authorized Supervisor	Personnel
A	4-19-10	N	N	N	Y	N	N	N	JKH	JKH
B	4-19-10	N	N	N	Y	N	N	N	JKH	JKH
C	4-19-10	N	N	N	Y	N	N	N	JKH	JKH
D	4-19-10	0%	BREACH @ DE LEVEE						JKH	JKH
E	4-19-10	0%	BREACH @ DE LEVEE & N FACE OF E (REPAIRED 2-9-09)						JKH	JKH
* PREP WORK STARTED FOR REPAIR OF "E" POND TO START ON 4-21-10										

EAGLE VALLEY GENERATING STATION
INDIANAPOLIS POWER & LIGHT COMPANY
MARTINSVILLE, INDIANA

CDM

FIGURE 9

Appendix A
USEPA Coal Combustion Dam
Inspection Checklist Forms



Site Name: IPL Eagle Valley Generating Station	Date: April 28, 2010
Unit Name: Pond A	Operator's Name: Indianapolis Power & Light Company
Unit I.D.: n/a	Hazard Potential Classification: High Significant Low
Inspector's Name: Michael Smith, Michael Schumaker	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

	Yes	No		Yes	No
1. Frequency of Company's Dam Inspections?		see note 1	18. Sloughing or bulging on slopes?	X	
2. Pool elevation (operator records)?		626.0	19. Major erosion or slope deterioration?		X
3. Decant inlet elevation (operator records)?		626.0	20. Decant Pipes:		
4. Open channel spillway elevation (operator records)?		625.0	Is water entering inlet, but not exiting outlet?		X
5. Lowest dam crest elevation (operator records)?		629.0	Is water exiting outlet, but not entering inlet?		X
6. If instrumentation is present, are readings recorded (operator records)?		d/n/a	Is water exiting outlet flowing clear?	X	
7. Is the embankment currently under construction?		X	21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below):		
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?		n/a	From underdrain?		X
9. Trees growing on embankment? (If so, indicate largest diameter below)		X	At isolated points on embankment slopes?		X
10. Cracks or scarps on crest?		X	At natural hillside in the embankment area?		X
11. Is there significant settlement along the crest?	X		Over widespread areas?		X
12. Are decant trashracks clear and in place?	X		From downstream foundation area?	X	
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?		X	"Boils" beneath stream or ponded water?		X
14. Clogged spillways, groin or diversion ditches?		X	Around the outside of the decant pipe?		X
15. Are spillway or ditch linings deteriorated?		X	22. Surface movements in valley bottom or on hillside?		X
16. Are outlets of decant or underdrains blocked?		X	23. Water against downstream toe?	X	
17. Cracks or scarps on slopes?		X	24. Were Photos taken during the dam inspection?	X	

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

Inspection Issue #	Comments
1. Inspections performed by plant personnel every two weeks. Semi-annual detailed inspection by independent consultant.	
2. through 5. No operating records. Data based on design plans and field estimates.	
4/11. Emergency overflow spillway according to IPL personnel. Not in design documents. No apparent settlement.	
8. Plans do not indicate if foundation was prepared.	
9. Brush growing. Largest diameter ~3 inches on south embankment exterior slope.	
11. Low spots on east embankment crest from truck traffic hauling ash to Pond E.	
18. Sloughing and surface erosion on west embankment above Pond B and C.	
21. Moist, soft area at fence-line on south embankment exterior slope.	
23. Ponds B & C located at exterior toe of Pond A west embankment.	

n/a = Not Available
d/n/a = Does Not Apply

**Coal Combustion Waste (CCW)
Impoundment Inspection**Impoundment NPDES Permit # IN0004693
Date April 28, 2010Michael Smith
INSPECTOR Michael SchumakerImpoundment Name Pond A
Impoundment Company Indianapolis Power & Light Company (IPL)
EPA Region 5
State Agency (Field Office) Addresss 402 West Washington Street, Room W264
Indianapolis, IN 46204Name of Impoundment Pond A
(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)New X Update _____Is impoundment currently under construction? _____
Is water or ccw currently being pumped into the impoundment? X _____Yes _____ No X
X _____**IMPOUNDMENT FUNCTION:** Fly Ash, bottom ash, boiler slag, waste water, drainageNearest Downstream Town : Name Martinsville, Indiana
Distance from the impoundment 5 miles south

Impoundment

Location: Longitude 86 Degrees 25 Minutes 36.64 Seconds W
Latitude 39 Degrees 28 Minutes 51.55 Seconds N
State Indiana County MorganDoes a state agency regulate this impoundment? YES _____ NO X*

If So Which State Agency? _____

*Indiana Department of Natural Resources (IDNR) is responsible for the State's dam safety program, however IDNR has not been actively involved in the regulation of Coal Combustion Waste Impoundments to date. The owner indicates there are no State inspection reports for this impoundment.

HAZARD POTENTIAL (In the event the impoundment should fail, the following would occur):

_____ **LESS THAN LOW HAZARD POTENTIAL:** Failure or misoperation of the dam results in no probable loss of human life or economic or environmental losses.

_____ **LOW HAZARD POTENTIAL:** Dams assigned the low hazard potential classification are those where failure or misoperation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner's property.


 X **SIGNIFICANT HAZARD POTENTIAL:** Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.

_____ **HIGH HAZARD POTENTIAL:** Dams assigned the high hazard potential classification are those where failure or misoperation will probably cause loss of human life.

DESCRIBE REASONING FOR HAZARD RATING CHOSEN:

- A.) A breach would damage the railroad.
- B.) A breach would have an environmental impact on the White River, Discharge Canal, and downstream area.
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____

CONFIGURATION:



☐ Cross-Valley

☐ Side-Hill

☒ Diked

☐ Incised (form completion optional)

☐ Combination Incised/Diked

Embankment Height 26 feet

Pool Area 19 acres

Current Freeboard 3 feet

Embankment Material Compacted Fill & Ash

Liner None

Liner Permeability N/A

TYPE OF OUTLET (Mark all that apply)

 Open Channel Spillway


 Trapezoidal

 X Triangular


 Rectangular

 Irregular

TRAPEZOIDAL



TRIANGULAR




 1 depth


 bottom (or average) width

 50 top width

RECTANGULAR



IRREGULAR



 X **Outlet**

 2 - 30" inside diameter

Material


 X corrugated metal

 welded steel

 concrete

 plastic (hdpe, pvc, etc.)

 other (specify) _____



Is water flowing through the outlet? YES X NO

 No Outlet

 Other Type of Outlet (specify) _____

The Impoundment was Designed By Professional Engineers at IPL Corporate

YES _____ NO X

DRAFT



Site Name: IPL Eagle Valley Generating Station	Date: April 28, 2010
Unit Name: Pond B	Operator's Name: Indianapolis Power & Light Company
Unit I.D.: n/a	Hazard Potential Classification: High Significant Low
Inspector's Name: Michael Smith, Michael Schumaker	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

		Yes	No			Yes	No
1. Frequency of Company's Dam Inspections?	see note 1			18. Sloughing or bulging on slopes?			X
2. Pool elevation (operator records)?	616.0			19. Major erosion or slope deterioration?			X
3. Decant inlet elevation (operator records)?	616.0			20. Decant Pipes:			
4. Open channel spillway elevation (operator records)?	d/n/a			Is water entering inlet, but not exiting outlet?			X
5. Lowest dam crest elevation (operator records)?	619.0			Is water exiting outlet, but not entering inlet?			X
6. If instrumentation is present, are readings recorded (operator records)?	d/n/a			Is water exiting outlet flowing clear?	X		
7. Is the embankment currently under construction?			X	21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below):			
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?	n/a			From underdrain?			X
9. Trees growing on embankment? (If so, indicate largest diameter below)			X	At isolated points on embankment slopes?			X
10. Cracks or scarps on crest?			X	At natural hillside in the embankment area?			X
11. Is there significant settlement along the crest?			X	Over widespread areas?			X
12. Are decant trashracks clear and in place?	X			From downstream foundation area?			X
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?			X	"Boils" beneath stream or ponded water?			X
14. Clogged spillways, groin or diversion ditches?			X	Around the outside of the decant pipe?			X
15. Are spillway or ditch linings deteriorated?			X	22. Surface movements in valley bottom or on hillside?			X
16. Are outlets of decant or underdrains blocked?			X	23. Water against downstream toe?	X		
17. Cracks or scarps on slopes?			X	24. Were Photos taken during the dam inspection?	X		

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

Inspection Issue #

Comments

1. Inspections performed by plant personnel every two weeks. Semi-annual detailed inspection by independent consultant.
2. through 5. No operating records. Data based on design plans and field estimates.
8. Plans do not indicate if foundation was prepared.
23. Pond C located at exterior toe of Pond B north embankment and at exterior toe of Pond A west embankment.

n/a = Not Available
d/n/a = Does Not Apply

**Coal Combustion Waste (CCW)
Impoundment Inspection**

Impoundment NPDES Permit # IN0004693 Michael Smith
Date April 28, 2010 INSPECTOR Michael Schumaker

Impoundment Name Pond B
Impoundment Company Indianapolis Power & Light Company (IPL)
EPA Region 5
State Agency (Field Office) Addresss 402 West Washington Street, Room W264
Indianapolis, IN 46204

Name of Impoundment Pond B
(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)

New X Update _____

Is impoundment currently under construction? _____
Is water or ccw currently being pumped into the impoundment? _____

Yes	No
_____	<u>X</u>
<u>X</u>	_____

IMPOUNDMENT FUNCTION: Fly Ash, bottom ash, boiler slag, waste water, drainage

Nearest Downstream Town : Name Martinsville, Indiana
Distance from the impoundment 5 miles south

Impoundment

Location: Longitude 86 Degrees 25 Minutes 37 Seconds W
Latitude 39 Degrees 28 Minutes 57.15 Seconds N
State Indiana County Morgan

Does a state agency regulate this impoundment? YES _____ NO X*

If So Which State Agency? _____

*Indiana Department of Natural Resources (IDNR) is responsible for the State's dam safety program, however IDNR has not been actively involved in the regulation of Coal Combustion Waste Impoundments to date. The owner indicates there are no State inspection reports for this impoundment.

HAZARD POTENTIAL (In the event the impoundment should fail, the following would occur):

_____ **LESS THAN LOW HAZARD POTENTIAL:** Failure or misoperation of the dam results in no probable loss of human life or economic or environmental losses.

_____ LOW HAZARD POTENTIAL: Dams assigned the low hazard potential classification are those where failure or misoperation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner's property.

X **SIGNIFICANT HAZARD POTENTIAL:** Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.

_____ **HIGH HAZARD POTENTIAL:** Dams assigned the high hazard potential classification are those where failure or misoperation will probably cause loss of human life.


DESCRIBE REASONING FOR HAZARD RATING CHOSEN:

A.) A breach could result in the failure of Pond A or Pond C.

B.) A breach would have an environmental impact on the White River, Discharge Canal, and downstream area.

[illegible]

CONFIGURATION:



☐ Cross-Valley

☐ Side-Hill

☒ Diked

☐ Incised (form completion optional)

☐ Combination Incised/Diked

Embankment Height 16 feet

Pool Area 13 acres

Current Freeboard 3 feet

Embankment Material Compacted Fill & Ash

Liner None

Liner Permeability N/A

TYPE OF OUTLET (Mark all that apply)

☐ **Open Channel Spillway**

☐ Trapezoidal

☐ Triangular

☐ Rectangular

☐ Irregular


☐ depth

☐ bottom (or average) width


☐ top width

☐


TRAPEZOIDAL




TRIANGULAR



RECTANGULAR



IRREGULAR



☒ **Outlet**

2 - 30" inside diameter

Material

☒ corrugated metal

☐ welded steel

☐ concrete

☐ plastic (hdpe, pvc, etc.)

☐ other (specify) _____

Is water flowing through the outlet? YES ☒ NO _____

☐ **No Outlet**

☐ **Other Type of Outlet** (specify) _____

The Impoundment was Designed By Professional Engineers at IPL Corporate

YES _____ NO X

DRAFT



Site Name: IPL Eagle Valley Generating Station	Date: April 28, 2010
Unit Name: Pond C	Operator's Name: Indianapolis Power & Light Company
Unit I.D.: n/a	Hazard Potential Classification: High Significant Low
Inspector's Name: Michael Smith, Michael Schumaker	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

		Yes	No			Yes	No
1. Frequency of Company's Dam Inspections?	see note 1			18. Sloughing or bulging on slopes?			X
2. Pool elevation (operator records)?	610.0			19. Major erosion or slope deterioration?	X		
3. Decant inlet elevation (operator records)?	610.0			20. Decant Pipes:			
4. Open channel spillway elevation (operator records)?	d/n/a			Is water entering inlet, but not exiting outlet?			X
5. Lowest dam crest elevation (operator records)?	619.0			Is water exiting outlet, but not entering inlet?			X
6. If instrumentation is present, are readings recorded (operator records)?	d/n/a			Is water exiting outlet flowing clear?	X		
7. Is the embankment currently under construction?		X		21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below):			
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?	n/a			From underdrain?			X
9. Trees growing on embankment? (If so, indicate largest diameter below)		X		At isolated points on embankment slopes?			X
10. Cracks or scarps on crest?		X		At natural hillside in the embankment area?			X
11. Is there significant settlement along the crest?		X		Over widespread areas?			X
12. Are decant trashracks clear and in place?	X			From downstream foundation area?			X
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?		X		"Boils" beneath stream or ponded water?			X
14. Clogged spillways, groin or diversion ditches?		X		Around the outside of the decant pipe?			X
15. Are spillway or ditch linings deteriorated?		X		22. Surface movements in valley bottom or on hillside?			X
16. Are outlets of decant or underdrains blocked?		X		23. Water against downstream toe?			X
17. Cracks or scarps on slopes?		X		24. Were Photos taken during the dam inspection?	X		

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

Inspection Issue #

Comments

1. Inspections performed by plant personnel every two weeks. Semi-annual detailed inspection by independent consultant.
2. through 5. No operating records. Data based on design plans and field estimates.
8. Plans do not indicate if foundation was prepared.
19. Erosion on west embankment interior slope from diversion boom cable. Erosion rill on north embankment interior slope at east extent.

n/a = Not Available
d/n/a = Does Not Apply



**Coal Combustion Waste (CCW)
Impoundment Inspection**

Impoundment NPDES Permit # IN0004693 Michael Smith
Date April 28, 2010 INSPECTOR Michael Schumaker

Impoundment Name Pond C
Impoundment Company Indianapolis Power & Light Company (IPL)
EPA Region 5
State Agency (Field Office) Addresss 402 West Washington Street, Room W264
Indianapolis, IN 46204

Name of Impoundment Pond C
(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)

New X Update _____

Is impoundment currently under construction? _____
Is water or ccw currently being pumped into the impoundment? _____

Yes	No
_____	<u>X</u>
<u>X</u>	_____

IMPOUNDMENT FUNCTION: Fly Ash, bottom ash, boiler slag, waste water, drainage

Nearest Downstream Town : Name Martinsville, Indiana
Distance from the impoundment 5 miles south

Impoundment

Location: Longitude 86 Degrees 25 Minutes 37.9 Seconds W
Latitude 39 Degrees 29 Minutes 2.71 Seconds N
State Indiana County Morgan

Does a state agency regulate this impoundment? YES _____ NO X*

If So Which State Agency? _____

*Indiana Department of Natural Resources (IDNR) is responsible for the State's dam safety program, however IDNR has not been actively involved in the regulation of Coal Combustion Waste Impoundments to date. The owner indicates there are no State inspection reports for this impoundment.

HAZARD POTENTIAL (In the event the impoundment should fail, the following would occur):

_____ **LESS THAN LOW HAZARD POTENTIAL:** Failure or misoperation of the dam results in no probable loss of human life or economic or environmental losses.

_____ **LOW HAZARD POTENTIAL:** Dams assigned the low hazard potential classification are those where failure or misoperation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner's property.


 X **SIGNIFICANT HAZARD POTENTIAL:** Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.

_____ **HIGH HAZARD POTENTIAL:** Dams assigned the high hazard potential classification are those where failure or misoperation will probably cause loss of human life.

DESCRIBE REASONING FOR HAZARD RATING CHOSEN:

- A.) A breach could result in the failure of Pond A or Pond B.
- B.) A breach would have an environmental impact on the White River, Discharge Canal, and downstream area.
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____
- _____

CONFIGURATION:



☐ Cross-Valley

☐ Side-Hill

☒ Diked

☐ Incised (form completion optional)

☐ Combination Incised/Diked

Embankment Height 16 feet

Pool Area 8 acres

Current Freeboard 9 feet

Embankment Material Compacted Fill & Ash

Liner None

Liner Permeability N/A

TYPE OF OUTLET (Mark all that apply)

☐ **Open Channel Spillway**

☐ Trapezoidal

☐ Triangular

☐ Rectangular

☐ Irregular


☐ depth

☐ bottom (or average) width


☐ top width

☐


TRAPEZOIDAL




TRIANGULAR



RECTANGULAR



IRREGULAR



☒ **Outlet**

1 - 24" inside diameter

Material

☐ corrugated metal

☒ welded steel

☒ concrete

☐ plastic (hdpe, pvc, etc.)

☐ other (specify) _____

Is water flowing through the outlet? YES ☒ NO _____

☐ **No Outlet**

☒ **Other Type of Outlet** (specify) Outlet structure with stop logs and butterfly valve

The Impoundment was Designed By Professional Engineers at IPL Corporate

YES _____ NO X

DRAFT



Site Name: IPL Eagle Valley Generating Station	Date: April 29, 2010
Unit Name: Pond D	Operator's Name: Indianapolis Power & Light Company
Unit I.D.: n/a	Hazard Potential Classification: High Significant Low
Inspector's Name: Michael Smith, Michael Schumaker	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

	Yes	No		Yes	No
1. Frequency of Company's Dam Inspections?		see note 1	18. Sloughing or bulging on slopes?		X
2. Pool elevation (operator records)?		see note 2	19. Major erosion or slope deterioration?	X	
3. Decant inlet elevation (operator records)?		625.0	20. Decant Pipes:		
4. Open channel spillway elevation (operator records)?		d/n/a	Is water entering inlet, but not exiting outlet?	d/n/a	
5. Lowest dam crest elevation (operator records)?		643.0	Is water exiting outlet, but not entering inlet?	d/n/a	
6. If instrumentation is present, are readings recorded (operator records)?		X	Is water exiting outlet flowing clear?	d/n/a	
7. Is the embankment currently under construction?	X		21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below):		
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?		n/a	From underdrain?		X
9. Trees growing on embankment? (If so, indicate largest diameter below)		X	At isolated points on embankment slopes?		X
10. Cracks or scarps on crest?		X	At natural hillside in the embankment area?		X
11. Is there significant settlement along the crest?		X	Over widespread areas?		X
12. Are decant trashracks clear and in place?	X		From downstream foundation area?		X
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?		X	"Boils" beneath stream or ponded water?		X
14. Clogged spillways, groin or diversion ditches?		X	Around the outside of the decant pipe?		X
15. Are spillway or ditch linings deteriorated?		X	22. Surface movements in valley bottom or on hillside?		X
16. Are outlets of decant or underdrains blocked?		X	23. Water against downstream toe?		X
17. Cracks or scarps on slopes?		X	24. Were Photos taken during the dam inspection?	X	

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

Inspection Issue #

Comments

1. Inspections performed by plant personnel every two weeks. Semi-annual detailed inspection by independent consultant.
2. Pond D is currently dry. Design elevation is El. 625.
2. through 6. No operating records. Data based on design plans and field estimates. Pond under construction. Piezometers not read by Eagle Valley personnel.
3. Outlet pipeline from Pond D is being routed through Pond E to existing outlet structure in Pond E.
7. Divider embankment is being reconstructed after 1/30/08 breach.
8. Plans do not indicate if foundation was prepared for existing embankment. New embankment foundation prepared.
19. Divider embankment D/E breached on 1/30/08. Embankment being reconstructed. Repair designed by independent consultant Professional Engineer.
- 20 & 21. Impoundment is drained for repair. Until repairs are complete, impoundment cannot store water.

n/a = Not Available
d/n/a = Does Not Apply



**Coal Combustion Waste (CCW)
Impoundment Inspection**

Impoundment NPDES Permit # IN0004693 Michael Smith
Date April 29, 2010 INSPECTOR Michael Schumaker

Impoundment Name Pond D
Impoundment Company Indianapolis Power & Light Company (IPL)
EPA Region 5
State Agency (Field Office) Addresss 402 West Washington Street, Room W264
Indianapolis, IN 46204

Name of Impoundment Pond D
(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)

New X Update _____

	Yes	No
Is impoundment currently under construction?	<u>X</u>	_____
Is water or ccw currently being pumped into the impoundment?	_____	<u>X</u>

IMPOUNDMENT FUNCTION: Emergency use, usually not active. Fly Ash, bottom ash, boiler slag, waste water, drainage

Nearest Downstream Town : Name Martinsville, Indiana

Distance from the impoundment 5 miles south

Impoundment

Location: Longitude 86 Degrees 25 Minutes 20.87 Seconds W
Latitude 39 Degrees 28 Minutes 59.12 Seconds N
State Indiana County Morgan

Does a state agency regulate this impoundment? YES _____ NO X*

If So Which State Agency? _____

*Indiana Department of Natural Resources (IDNR) is responsible for the State's dam safety program, however IDNR has not been actively involved in the regulation of Coal Combustion Waste Impoundments to date. The owner indicates there are no State inspection reports for this impoundment.

HAZARD POTENTIAL (In the event the impoundment should fail, the following would occur):

_____ **LESS THAN LOW HAZARD POTENTIAL:** Failure or misoperation of the dam results in no probable loss of human life or economic or environmental losses.

_____ **LOW HAZARD POTENTIAL:** Dams assigned the low hazard potential classification are those where failure or misoperation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner's property.


_____ **SIGNIFICANT HAZARD POTENTIAL:** Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.

 X **HIGH HAZARD POTENTIAL:** Dams assigned the high hazard potential classification are those where failure or misoperation will probably cause loss of human life.

DESCRIBE REASONING FOR HAZARD RATING CHOSEN:

- A.) A breach could result in the failure of Pond E.
 - B.) A breach would have an environmental impact on the White River, Discharge Canal, and downstream area.
 - C.) A breach could damage the railroad.
 - D. A breach or misoperation could cause loss of life at the plant.
- _____

CONFIGURATION:



☐ Cross-Valley

☐ Side-Hill

☒ Diked

☐ Incised (form completion optional)

☐ Combination Incised/Diked

Embankment Height 38 feet

Pool Area 16 acres

Current Freeboard Pond is dry feet

Embankment Material Earthen/Ash

Liner None

Liner Permeability N/A

TYPE OF OUTLET (Mark all that apply)

_____ **Open Channel Spillway**

_____ Trapezoidal

_____ Triangular

_____ Rectangular


_____ Irregular

_____ depth


_____ bottom (or average) width

_____ top width


TRAPEZOIDAL




TRIANGULAR



RECTANGULAR



IRREGULAR



 X **Outlet**

 1 - 30" inside diameter

Material

_____ corrugated metal

_____ welded steel

_____ concrete

HDPE plastic (hdpe, pvc, etc.)

_____ other (specify) _____

Is water flowing through the outlet? YES _____ NO Under construction.

_____ **No Outlet**

_____ **Other Type of Outlet** (specify) _____

The Impoundment was Designed By Prior to 2007 by Professional Engineers at IPL
Corporate. 2007 repair by FMSM. 2008 repair by BT² Engineering.

Has there ever been significant seepages at this site? YES X NO

If So When? Prior to 2007.

IF So Please Describe: Seepage was previously identified on the north embankment exterior slope. A toe drain along the north/northeast embankment toe was installed at some point in time. There are no as-built records on the toe drain. No active seepage was observed in the area of the toe drain and no flowing water was observed at the toe drain outlet sump pit. Pond D is currently dry.

(This section contains horizontal lines for additional text and a large diagonal 'DRAFT' watermark.)

YES _____ NO X

DRAFT



Site Name: IPL Eagle Valley Generating Station	Date: April 29, 2010
Unit Name: Pond E	Operator's Name: Indianapolis Power & Light Company
Unit I.D.: n/a	Hazard Potential Classification: High Significant Low
Inspector's Name: Michael Smith, Michael Schumaker	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

		Yes	No			Yes	No
1. Frequency of Company's Dam Inspections?	see note 1			18. Sloughing or bulging on slopes?			X
2. Pool elevation (operator records)?	d/n/a			19. Major erosion or slope deterioration?	X		
3. Decant inlet elevation (operator records)?	620.7			20. Decant Pipes:			
4. Open channel spillway elevation (operator records)?	d/n/a			Is water entering inlet, but not exiting outlet?	d/n/a		
5. Lowest dam crest elevation (operator records)?	633.0			Is water exiting outlet, but not entering inlet?	d/n/a		
6. If instrumentation is present, are readings recorded (operator records)?			X	Is water exiting outlet flowing clear?	d/n/a		
7. Is the embankment currently under construction?	X			21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below):			
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?	n/a			From underdrain?			X
9. Trees growing on embankment? (If so, indicate largest diameter below)			X	At isolated points on embankment slopes?			X
10. Cracks or scarps on crest?			X	At natural hillside in the embankment area?			X
11. Is there significant settlement along the crest?			X	Over widespread areas?			X
12. Are decant trashracks clear and in place?	X			From downstream foundation area?			X
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?			X	"Boils" beneath stream or ponded water?			X
14. Clogged spillways, groin or diversion ditches?			X	Around the outside of the decant pipe?			X
15. Are spillway or ditch linings deteriorated?			X	22. Surface movements in valley bottom or on hillside?			X
16. Are outlets of decant or underdrains blocked?			X	23. Water against downstream toe?			X
17. Cracks or scarps on slopes?			X	24. Were Photos taken during the dam inspection?	X		

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

- | Inspection Issue # | Comments |
|---|----------|
| 1. Inspections performed by plant personnel every two weeks. Semi-annual detailed inspection by independent consultant. | |
| 2. Pond is being backfilled with compacted ash. | |
| 3. Outlet pipeline from Pond D will be routed through Pond E to pipeline connected to Pond C. | |
| 4. through 6. No operating records. Data based on design plans and field estimates. Pond under construction. Piezometers not read by Eagle Valley personnel. | |
| 7. Divider embankment D/E and Pond E north embankment are being reconstructed after 1/30/08 breach. Pond E is being filled with compacted ash (Pond E is being filled but not being closed). | |
| 8. Plans do not indicate if foundation was prepared for existing embankment. Embankment foundation prepared for repair work. | |
| 19. Divider embankment D/E breached on 1/30/08. Breach resulted in Pond E north embankment being overtopped. North embankment breached. Large erosion features on west and north embankment exterior slope. Embankment and erosion being repaired. Repair designed by independent consultant Professional Engineer. | |
| 20 & 21. Impoundment is drained for reconstruction and is being filled with ash. | |

**Coal Combustion Waste (CCW)
Impoundment Inspection**Impoundment NPDES Permit # IN0004693
Date April 29, 2010Michael Smith
INSPECTOR Michael SchumakerImpoundment Name Pond E
Impoundment Company Indianapolis Power & Light Company (IPL)
EPA Region 5
State Agency (Field Office) Addresss 402 West Washington Street, Room W264
Indianapolis, IN 46204Name of Impoundment Pond E
(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)New X Update _____

Is impoundment currently under construction?

Yes

X

No

Is water or ccw currently being pumped into the impoundment?

X**IMPOUNDMENT FUNCTION:** Fly ash, bottom ash, boiler slagNearest Downstream Town : Name Martinsville, IndianaDistance from the impoundment 5 miles south

Impoundment

Location: Longitude 86 Degrees 25 Minutes 24.11 Seconds W
Latitude 39 Degrees 28 Minutes 03.81 Seconds N
State Indiana County MorganDoes a state agency regulate this impoundment? YES _____ NO X*

If So Which State Agency? _____

*Indiana Department of Natural Resources (IDNR) is responsible for the State's dam safety program, however IDNR has not been actively involved in the regulation of Coal Combustion Waste Impoundments to date. The owner indicates there are no State inspection reports for this impoundment.

HAZARD POTENTIAL (In the event the impoundment should fail, the following would occur):

_____ **LESS THAN LOW HAZARD POTENTIAL:** Failure or misoperation of the dam results in no probable loss of human life or economic or environmental losses.

_____ LOW HAZARD POTENTIAL: Dams assigned the low hazard potential classification are those where failure or misoperation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner's property.

X **SIGNIFICANT HAZARD POTENTIAL:** Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.

_____ **HIGH HAZARD POTENTIAL:** Dams assigned the high hazard potential classification are those where failure or misoperation will probably cause loss of human life.


DESCRIBE REASONING FOR HAZARD RATING CHOSEN:

A.) A breach could result in the failure of Pond D.

B.) A breach would have an environmental impact on the White River, Discharge Canal, and downstream area.

C.) A breach could damage the railroad.

CONFIGURATION:



☐ Cross-Valley

☐ Side-Hill

☒ Diked

☐ Incised (form completion optional)

☐ Combination Incised/Diked

Embankment Height 28 feet

Pool Area 4 acres

Current Freeboard Pond is dry feet

Embankment Material Compacted fill & Ash

Liner None

Liner Permeability N/A

TYPE OF OUTLET (Mark all that apply)

☐ **Open Channel Spillway**

☐ Trapezoidal

☐ Triangular

☐ Rectangular

☐ Irregular


☐ depth

☐ bottom (or average) width


☐ top width

☐


TRAPEZOIDAL




TRIANGULAR



RECTANGULAR



IRREGULAR



☒ **Outlet**

1 - 24" inside diameter

Material

☐ corrugated metal


☐ welded steel

☒ concrete

☐ plastic (hdpe, pvc, etc.)

☐ other (specify) _____

☐



Is water flowing through the outlet? YES _____ NO Under construction.

☐ **No Outlet**

☐ **Other Type of Outlet** (specify) _____

The Impoundment was Designed By Prior to 2007 by Professional Engineers at IPL
Corporate. 2007 repair by FMSM. 2008 repair by BT² Engineering.

Has there ever been any measures undertaken to monitor/lower Phreatic water table levels based on past seepages or breaches at this site? YES _____ NO X

If so, which method (e.g., piezometers, gw pumping,...)? _____

If so Please Describe : _____

DRAFT

DRAFT

Appendix B Photographs



1. Pond A – East embankment exterior slope looking south.



2. Pond A – East embankment crest looking south.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN

CDM Project No.: 76658.1801.034.SIT.EAGLE

April 28 and 29, 2010



3. Pond A – East embankment exterior slope. Erosion control blanket installed near northeast corner looking southeast. Note: Blanket appears to be improperly staked, there are 1- to 3-inch gaps beneath the blanket, and there is no apparent anchor trench or roll overlap.



4. Pond A – East embankment exterior slope. Erosion control blanket installed near northeast corner looking northwest.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



5. Pond A – East exterior slope looking south. Low spot and minor slough at toe of slope.. Possible tractor rutting.



6. Overview of two 10-inch-diameter HDPE discharge pipes into Pond A, looking northwest.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



7. Pond A – depression near crest of east embankment, looking north.



8. Overview of three 10-inch-diameter HDPE discharge pipes into Pond A, looking southwest.
Note two right-most pipes are disconnected.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



9. Overview of Pond D west embankment exterior slope from toe of Pond A east embankment. Note change in vegetation type at the three vertical expansions.



10. Overview of 10-inch-diameter HDPE discharge pipe into Pond A, looking west.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



11. Overview of ash excavation in Pond A looking west. Ash being used as fill to repair Ponds D and E..



12. Pond A looking north - Possible former seep location at toe of east embankment.,.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



13. Overview of Pond A from crest of southeast corner looking northwest.



14. Pond A - Depression in crest from truck traffic, looking south.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



15. Pond A – East embankment exterior slope looking north.



16. Pond A – East crest looking north.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN

CDM Project No.: 76658.1801.034.SIT.EAGLE

April 28 and 29, 2010



17. Pond A – Downstream area of east embankment looking southeast.



18. Pond A – Downstream area of east embankment at southeast corner of embankment looking south.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



19. Pond A – South embankment crest looking west.



20. Pond A – South embankment exterior slope looking west.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN

CDM Project No.: 76658.1801.034.SIT.EAGLE

April 28 and 29, 2010



21. Pond A – Soft spongy area at toe of south embankment under tree canopy (possible former active seepage area).



22. Pond A – South embankment crest, looking west.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



23. Pond A – South embankment exterior slope, looking southeast.



24. Pond A – South embankment crest, looking southeast.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



25. Pond A – West embankment exterior slope, looking north.



26. Pond A – Erosion rill on west embankment exterior slope, looking east.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN

CDM Project No.: 76658.1801.034.SIT.EAGLE

April 28 and 29, 2010



27. Pond A – West embankment crest, looking south.



Emergency overflow
spillway

28. Pond A/B – north slope of divider embankment, looking east.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



29. Pond A/B - south slope of divider embankment, looking east.



30. Pond A/B - crest of divider embankment, looking east.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



31. Overview of Pond B & C from crest of Pond A, looking northeast.



32. Depression in north slope of Pond A/B divider embankment.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



33. North slope of divider embankment A/B and Pond B west embankment, looking southwest.



34. Crest of divider embankment A/B, looking northeast.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



35. Erosion feature and depression in north slope of divider embankment A/B.



36. Depression in north slope of divider embankment A/B.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



37. Depression in northwest slope of divider embankment A/B.



38. Northwest slope of divider embankment A/B, looking south.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



39. Crest of divider embankment B/C from crest of Pond A, looking west.



40. West slope of divider embankment A/C from Pond B, looking north.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



41. Minor sloughing and erosion feature on west slope of divider embankment A/C.



42. West slope of divider embankment A/C from Pond C north embankment, looking south.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



43. Crest of divider embankment A/C from Pond C north embankment, looking south.



44. Pond A – North embankment crest, looking east.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN

CDM Project No.: 76658.1801.034.SIT.EAGLE

April 28 and 29, 2010



45. Pond A – North embankment exterior slope, looking east.



46. Pond C – North embankment exterior slope, looking west.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



47. Pond C – North embankment interior slope and crest, looking west. Note erosion rill on interior slope.



48. Pond C – North embankment crest, looking east.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



49. Pond C - North embankment interior slope, looking east. Note brush and limited riprap on slope.



50. Pond C - North embankment exterior slope, looking east.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



51. Pond C - West embankment interior slope, looking south.



52. Pond C - West embankment crest, looking south.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



53. Pond C – West embankment exterior slope, looking south.



54. Pond C – Outlet structure gatehouse. Note stoplogs and butterfly valve in catwalk.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



55. Pond C - Erosion feature from diversion boom tie line.



56. Pond C - West embankment crest, looking north



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



57. Crest of divider embankment B/C, looking east.



58. South slope of divider embankment B/C, looking east.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



59. North slope of divider embankment B/C looking east.



60. Pond B – west embankment crest, looking south.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



61. Pond B – west embankment exterior slope, looking south.



62. Pond B – west embankment interior slope, looking north



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN

CDM Project No.: 76658.1801.034.SIT.EAGLE

April 28 and 29, 2010



63. Pond B – west embankment crest, looking north



64. Pond B – west embankment exterior slope, looking north



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



65. Pond B - erosion rill on exterior slope recently filled in with riprap, looking east.



66. Pond C - Outlet structure outfall to discharge canal, looking south.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



67. Pond D – east embankment exterior slope, looking southwest.



68. Pond D – east embankment crest, looking southwest.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



69. Pond D - north embankment crest, looking northwest.



70. Pond D - north embankment toe drain sump pit located in northeast downstream area.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN

CDM Project No.: 76658.1801.034.SIT.EAGLE

April 28 and 29, 2010



71. Pond D – East embankment downstream area looking southeast. Note new piping for Ponds D & E.



72. Pond D – Erosion rill and depression on east embankment buttress berm, looking south.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



73. Pond D – Erosion rill on east embankment buttress berm, looking northeast



74. Pond D – Crest of east embankment buttress berm, looking north



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN

CDM Project No.: 76658.1801.034.SIT.EAGLE

April 28 and 29, 2010



75. Pond D – Crest of east embankment buttress berm, looking south



76. Pond D – Southeast embankment exterior slope, looking southwest.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



77. Pond D - Southeast embankment crest, looking southwest.



78. Piezometer PZ-2 on Pond D east embankment crest installed by BT² on 6/12/08.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN

CDM Project No.: 76658.1801.034.SIT.EAGLE

April 28 and 29, 2010



79. Pond D – Southeast embankment interior area, looking southwest



80. Pond D - Large bare spot on upper third of southeast embankment exterior slope, looking northwest.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN

CDM Project No.: 76658.1801.034.SIT.EAGLE

April 28 and 29, 2010



81. Typical bare spots on upper third of Pond D exterior embankment (last expansion).



82. Pond D - Erosion rill on southeast embankment exterior slope, looking northwest.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



83. Pond D – Southeast embankment exterior slope, looking northeast.



84. Pond D – Southeast embankment crest, looking northeast.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



85. Pond D – Erosion rill on southeast embankment exterior slope, looking southeast.



86. Pond D – Southwest corner of southeast embankment exterior slope downstream area, looking southeast.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



87. Pond D - West embankment crest, looking north



88. Pond D - West embankment interior slope, looking north.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



89. Pond D – West embankment exterior slope, looking north. Note bands of vegetation from the vertical expansions. Bare spots observed on upper third.



90. Pond D – Typical bare spots on upper third of west embankment exterior slope, looking south.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



91. Pond D – West embankment exterior slope, looking south.



92. Pond D – West embankment interior slope, looking south at edge of ash limit prior to Pond D/E embankment failure.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



93. Pond D – West embankment interior slope, looking north toward divider embankment D/E.



94. Overview of Pond D, south slope of divider embankment D/E, and west slope of Pond D diversion embankment. Note breach (circled) in divider embankment D/E.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



95. Overview of Pond D and west slope of Pond D diversion embankment, looking east.



96. Pond D - West embankment typical interior slope with shale armor near crest.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



97. Pond D – Typical bare spot and erosion on west embankment exterior slope, looking southeast.



98. Pond D – West embankment exterior slope at toe, looking north.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



99. North slope of divider embankment D/E, looking east.



100. Crest of divider embankment D/E, looking east.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



101. South slope of divider embankment D/E, looking east.



102. Overview of cut in divider embankment D/E for repair work.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



103. North slope of divider embankment D/E, looking west.



104. Overview of Pond E backfilling operation and Pond E outlet structure, looking northwest.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN

CDM Project No.: 76658.1801.034.SIT.EAGLE

April 28 and 29, 2010



105. Pond E - West embankment exterior slope, looking north.



106. Pond E - 16'Wx4'Dx17'L erosion gully at toe of west embankment exterior slope from previous failure event. Note erosion is scheduled to be repaired.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



107. Pond E – 8'Wx4.5'Dx15'L erosion gulley at crest of west embankment exterior slope from previous failure event. Note erosion is scheduled to be repaired.



108. Overview of discharge manholes from Pond E into Pond C, looking northwest.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



109. Pond E – West embankment interior slope, looking south.



110. Pond E – West embankment crest, looking south.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



111. Pond E – West embankment exterior slope, looking south.



112. Pond E – 8'Wx3'Dx25'L erosion gulley at mid-slope of west embankment exterior slope from previous failure event. Note erosion is scheduled to be repaired.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



113. Pond E – two approximately 4'Wx3'Dx20'L erosion gulleys at mid-slope of west embankment exterior slope from previous failure event. Note erosion is scheduled to be repaired.



114. Pond E – Downstream area looking south toward failure repair (reconstruction of north embankment).



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



115. Pond E - Overview of outlet control structure with stoplogs and butterfly valve, looking northwest.



116. Pond E - Overview of north embankment reconstruction, looking east.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



117. Overview of divider embankment D/E reconstruction and Pond E filling operation, looking south.



118. Overview of divider embankment D/E reconstruction, looking south.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



119. Pond E – erosion feature on north embankment exterior slope from previous failure event.



120. Pond E – Overview of north embankment reconstruction, looking west.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



121. Crest of divider embankment D/E, looking south.



122. West slope of divider embankment D/E, looking south.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



123. East slope of divider embankment D/E, looking south.



124. Overview of divider embankment D/E reconstruction, looking west.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



125. West slope of divider embankment D/E, looking north. Note pipes removed from embankment after breach.



126. Pond D - Erosion rill on west slope of diversion embankment, looking southwest.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



127. Pond D - Erosion feature on east slope of diversion embankment, looking east.



128. Pond D - Limit of ash at end of diversion embankment prior to failure, looking southwest.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



129. Pond D – Crest of diversion embankment, looking north.



130. Pond D – Depression with piping on east slope of diversion embankment, looking northeast.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



131. Pond D - North embankment exterior slope, looking east.



132. Pond D - North embankment crest, looking east.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



133. Pond D - North embankment interior slope, looking east.



134. Pond D - Toe of north embankment, looking east. Note drainage ditch with seepage collector pipe.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



135. Pond D – North embankment exterior slope, looking southeast.



136. Overview of downstream area north of Pond D and Pond E. Note repair of erosion areas which resulted from breach.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



137. Pond D - Northeast embankment exterior slope, looking southeast.



138. Pond D - Northeast embankment crest, looking southeast.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



139. Pond D – Northeast embankment interior slope, looking southeast.



140. Overview of three 10-inch-diameter HDPE discharge pipes into Pond D, looking southwest.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



141. Pond D - Northeast embankment interior slope, looking northwest.



142. Pond D - Northeast embankment crest, looking northwest.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



143. Pond D - Northeast embankment exterior slope, looking northwest.



144. Access road and discharge canal adjacent to toe of Pond D, looking northwest.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN



145. Downstream area of Pond D northeast embankment, looking east.



146. Overview of typical discharge canal adjacent the north embankments of Ponds A, C, D, and E.



INDIANAPOLIS POWER & LIGHT COMPANY
EAGLE VALLEY GENERATING STATION
MARTINSVILLE, IN

Appendix C
Photo GPS Locations

Appendix C

Photo GPS Locations

Site: IPL Eagle Valley Generating Station

System: US State Plane 1983

Zone: Indiana West 1302

Datum: NAD 1983 (Consus)

Coordinate Units: Feet

Photo No.	Northing	Easting
1 and 2	1,543,724.35	3,138,521.78
3	1,543,656.13	3,138,510.32
4	1,543,603.59	3,138,555.22
5	1,543,405.39	3,138,526.61
6	1,543,270.13	3,138,477.08
7	1,543,135.76	3,138,477.58
8	1,542,878.99	3,138,435.61
9	1,542,852.72	3,138,493.47
10	1,542,704.42	3,138,412.83
11	1,542,684.55	3,138,421.44
12	1,542,179.67	3,138,436.85
13 and 16	1,542,034.42	3,138,389.96
14	1,542,075.03	3,138,400.5
15	1,542,024.14	3,138,417.73
17 and 18	1,541,968.85	3,138,418.05
19 and 20	1,541,998.01	3,138,346.89
21	1,541,943.92	3,138,156.19
22	1,541,944.92	3,137,334.99
23	1,542,182.81	3,137,035.99
24	1,542,197.05	3,137,070.36
25 and 26	1,542,211.29	3,137,020.51
27	1,542,327.56	3,137,102.51
28 and 29	1,542,338.39	3,137,143.13
30 and 31	1,542,308.	3,137,114.16
32	1,542,506.98	3,137,820.9
33	1,542,578.25	3,137,910.31
34	1,542,590.98	3,137,929.74
35	1,542,812.37	3,138,067.58
36	1,542,904.44	3,138,091.21
37	1,542,940.83	3,138,103.52
38, 39, and 40	1,543,177.34	3,138,239.04
41	1,543,550.93	3,138,279.92
42 and 43	1,543,714.7	3,138,278.71
44	1,543,731.39	3,138,301.4
45	1,543,759.5	3,138,287.82
46	1,543,777.46	3,138,487.96
47	1,543,749.03	3,138,211.98
48 and 50	1,543,745.97	3,137,779.66
49	1,543,726.09	3,137,779.65
51, 52, and 53	1,543,730.53	3,137,752.09
54	1,543,677.39	3,137,729.7
56	1,543,524.48	3,137,665.63
57, 58, and 59	1,543,248.57	3,137,522.36
60	1,543,221.76	3,137,527.13

Appendix C

Photo GPS Locations

Site: IPL Eagle Valley Generating Station

System: US State Plane 1983

Zone: Indiana West 1302

Datum: NAD 1983 (Consus)

Coordinate Units: Feet

Photo No.	Northing	Easting
61	1,543,248.08	3,137,490.37
62 and 63	1,542,477.64	3,137,152.74
64	1,542,490.73	3,137,163.95
65	1,542,496.09	3,137,134.06
66	1,543,842.49	3,137,769.45
67	1,543,430.99	3,139,729.52
68 and 69	1,543,439.08	3,139,698.29
70	1,543,487.25	3,139,843.73
71	1,543,355.19	3,139,793.91
72 and 73	1,543,166.46	3,139,799.91
74 and 75	1,543,081.92	3,139,651.69
76	1,542,880.82	3,139,609.81
77 and 78	1,542,916.59	3,139,556.43
79	1,542,934.69	3,139,523.09
80 and 81	1,542,831.54	3,139,531.16
82	1,542,759.24	3,139,413.97
83 and 84	1,542,248.15	3,138,816.22
85	1,542,235.44	3,138,761.94
86	1,542,244.39	3,138,724.45
87, 88, and 89	1,542,270.15	3,138,729.15
90	1,542,626.21	3,138,721.5
91	1,542,791.47	3,138,657.6
92, 93, and 94	1,542,857.21	3,138,778.42
95	1,542,884.1	3,138,816.68
96	1,543,077.29	3,138,846.65
97	1,543,163.94	3,138,761.42
98	1,543,418.22	3,138,716.36
99, 100, and 101	1,543,392.1	3,138,841.03
102	1,543,383.45	3,139,067.18
103 and 104	1,543,433.06	3,139,084.42
105	1,543,423.28	3,138,771.89
106	1,543,512.46	3,138,723.86
107	1,543,595.04	3,138,770.43
108	1,543,648.62	3,138,799.28
109, 110, and 111	1,543,652.1	3,138,804.81
112	1,543,682.25	3,138,788.52
113	1,543,730.84	3,138,772.95
114	1,543,812.68	3,138,779.48
115	1,543,717.59	3,138,866.98
116	1,543,743.89	3,138,952.33
117 and 118	1,543,747.36	3,139,135.1
119	1,543,808.16	3,139,192.92
120, 121, 122, and 123	1,543,724.66	3,139,313.03
124 and 125	1,543,382.61	3,139,258.73

Appendix C

Photo GPS Locations

Site: IPL Eagle Valley Generating Station

System: US State Plane 1983

Zone: Indiana West 1302

Datum: NAD 1983 (Consus)

Coordinate Units: Feet

Photo No.	Northing	Easting
126	1,543,188.92	3,139,289.02
127 and 128	1,542,981.47	3,139,284.07
129	1,543,019.94	3,139,286.84
130	1,543,167.72	3,139,297.94
131, 132, and 133	1,543,728.52	3,139,330.12
134	1,543,815.6	3,139,328.12
135	1,543,865.25	3,139,305.49
136	1,543,719.1	3,139,509.71
137	1,543,717.47	3,139,557.47
138, 139, and 140	1,543,689.72	3,139,535.69
141, 142, and 145	1,543,476.56	3,139,687.13
143	1,543,501.97	3,139,741.64
144	1,543,523.14	3,139,781.15
146	1,543,556.85	3,139,979.66